

Survey Date		09/01/2017																								
Survey Type		V - Vessel Based																								
Construction Activity		TIDO - Timber Dolphin Removal				Comments																				
Tide		Ebb																								
Source Location		Area 1B (Bent 26 approximately)																								
Sample Location	Upcurrent (Ambient)												Downcurrent													
Distance to Source	Approx. 500 - 1000 ft ¹												150 ft ²													
Sample ID	090117-TIDO-E-U												090117-TIDO-E-D													
Sample Time	10:23												10:09													
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene		
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260				
Unit	(ppm)	(ppb)												(ppm)	(ppb)											
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1		
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006		
Analytical Result ⁴	S	NS												NS												
	M	15.2	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	21.2	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND			
	B	NS												NS												

Notes: ¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected as close to turbidity curtain as practicable

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/05/2017																								
Survey Type		V - Vessel Based																								
Construction Activity		TIDO - Timber Dolphin Removal				Comments																				
Tide		Flood																								
Source Location		Area 1B																								
Sample Location		Upcurrent (Ambient)												Downcurrent												
Distance to Source		Approx. 500 - 1000 ft ¹												117 ft ²												
Sample ID		090517-TIDO-F-U												090517-TIDO-F-D												
Sample Time		10:39												10:24												
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene		
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260				
Unit	(ppm)	(ppb)												(ppm)	(ppb)											
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1		
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	-	-	-	-	16	0.0006	*	0.0007	8.2	5.6	8.0	66	-	-	-	-	16	0.0006		
Analytical Result ⁴	S	19	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	34	ND	ND	ND	ND	ND	ND	ND	ND	ND	14	ND		
	M	NS												NS												
	B	29	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	41.4	ND	ND	ND	ND	ND	ND	ND	ND	22	ND		

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected as close to turbidity curtain as practicable

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

Reported value exceeds the Water Quality Standard as stated in Condition 61 of NYSDEC Permit Facility ID 3-9903-00043/00012-14

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/06/2017																								
Survey Type		V - Vessel Based																								
Construction Activity		TIDO - Timber Dolphin Removal				Comments																				
Tide		Flood																								
Source Location		Area 1B																								
Sample Location		Upcurrent (Ambient)												Downcurrent												
Distance to Source		Approx. 500 - 1000 ft ¹												150 ft ²												
Sample ID		090617-TIDO-F-U												090617-TIDO-F-D												
Sample Time		10:25												10:06												
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene		
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260				
Unit	(ppm)	(ppb)												(ppm)	(ppb)											
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1		
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	-	-	-	-	16	0.0006	*	0.0007	8.2	5.6	8.0	66	-	-	-	-	16	0.0006		
Analytical Result ⁴	S	19.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	24.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		
	M	NS												NS												
	B	25	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	21.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected as close to turbidity curtain as practicable

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/07/2017																								
Survey Type		V - Vessel Based																								
Construction Activity		TIDO - Timber Dolphin Removal				Comments																				
Tide		Flood																								
Source Location		Area 1B Approx Bent 15																								
Sample Location		Upcurrent (Ambient)												Downcurrent												
Distance to Source		Approx. 500 - 1000 ft ¹												140 ft ²												
Sample ID		090717-TIDO-F-U												090717-TIDO-F-D												
Sample Time		09:54												09:34												
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene		
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260				
Unit	(ppm)	(ppb)												(ppm)	(ppb)											
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1		
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006		
Analytical Result ⁴	S	22	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	16.4	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		
	M	NS												NS												
	B	24.2	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	21	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected as close to turbidity curtain as practicable

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/08/2017																								
Survey Type		V - Vessel Based																								
Construction Activity		TIDO - Timber Dolphin Removal				Comments																				
Tide		Flood																								
Source Location		Area 1 B																								
Sample Location		Upcurrent (Ambient)												Downcurrent												
Distance to Source		Approx. 500 - 1000 ft ¹												150 ft ²												
Sample ID		090817-TIDO-F-U												090817-TIDO-F-D												
Sample Time		10:26												10:13												
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene		
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260				
Unit	(ppm)	(ppb)												(ppm)	(ppb)											
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1		
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006		
Analytical Result ⁴	S	NS												NS												
	M	31	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	25.6	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		
	B	NS												NS												

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected as close to turbidity curtain as practicable

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/09/2017																						
Survey Type		B - Barge Based																						
Construction Activity		SIDI - Silt Displacement			Comments			Sample collected from barge.																
Tide		Ebb																						
Source Location		Bent 169																						
Sample Location		Upcurrent (Ambient)											Downcurrent											
Distance to Source		Approx. 350 ft ¹											20 ft ²											
Sample ID		090917-SIDI-E-U											090917-SIDI-E-D											
Sample Time		09:20											09:09											
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260		
Unit	(ppm)	(ppb)											(ppm)	(ppb)										
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006
Analytical Result ⁴	S	22.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	15	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
	M	NS											NS											
	B	21.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	19	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected within 500 ft mixing zone

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

✓ ✓ ✗

First Page Only: Design Package No. or Description ENV - 1413	
No. <u>0</u>	Date <u>9-21-2017</u>
CHECK PRINT	
Dwg. Only: Checked against calcs. and calc. check Confirmed By _____ Date _____	
Originator <u>J. Cassone</u>	Date <u>09/21/2017</u>
Checker _____	Date _____
Backchecker _____	Date _____
Updater _____	Date _____
Rechecker _____	Date _____

Survey Date		09/11/2017																							
Survey Type		V - Vessel Based																							
Construction Activity		SIDI - Silt Displacement				Comments																			
Tide		Ebb																							
Source Location		Bent 165																							
Sample Location		Upcurrent (Ambient)												Downcurrent											
Distance to Source		Approx. 500 - 1000 ft ¹												500 ft ²											
Sample ID		091117-SIDI-E-U												091117-SIDI-E-D											
Sample Time		10:33												09:58											
Parameter		Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene
								Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260		
Unit		(ppm)	(ppb)											(ppm)	(ppb)										
Detection Limit ³		Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1
Water Quality Standard ³		*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006
Analytical Result ⁴	S	19.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	22	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
	M	27	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	40.7	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
	B	35.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	53.3	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND

Notes: ¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected at the edge of the 500 ft mixing zone

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/11/2017																								
Survey Type		V - Vessel Based																								
Construction Activity		TIDO - Timber Dolphin Removal				Comments																				
Tide		Flood																								
Source Location		Area 1B Bent 15																								
Sample Location		Upcurrent (Ambient)												Downcurrent												
Distance to Source		Approx. 500 - 1000 ft ¹												57 ft ²												
Sample ID		091117-TIDO-F-U												091117-TIDO-F-D												
Sample Time		11:28												11:12												
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene		
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260				
Unit	(ppm)	(ppb)												(ppm)	(ppb)											
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1		
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	-	-	-	-	16	0.0006	*	0.0007	8.2	5.6	8.0	66	-	-	-	-	16	0.0006		
Analytical Result ⁴	S	NS												NS												
	M	29.3	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	35.2	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		
	B	NS												NS												

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected as close to turbidity curtain as practicable

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/12/2017																								
Survey Type		V - Vessel Based																								
Construction Activity		TIDO - Timber Dolphin Removal				Comments																				
Tide		Flood																								
Source Location		Area 1B Bent 15																								
Sample Location		Upcurrent (Ambient)												Downcurrent												
Distance to Source		Approx. 500 - 1000 ft ¹												126 ft ²												
Sample ID		091217-TIDO-F-U												091217-TIDO-F-D												
Sample Time		11:08												10:53												
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene		
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260				
Unit	(ppm)	(ppb)												(ppm)	(ppb)											
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	-	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	-	0.1		
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	-	-	-	-	16	0.0006	*	0.0007	8.2	5.6	8.0	66	-	-	-	-	16	0.0006		
Analytical Result ⁴	S	NS												NS												
	M	54.7	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	59.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		
	B	NS												NS												

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected as close to turbidity curtain as practicable

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/13/2017																							
Survey Type		V - Vessel Based																							
Construction Activity		SIDI - Silt Displacement			Comments																				
Tide		Ebb																							
Source Location		Approx Bent 183, in line with P39 of new bridge.																							
Sample Location		Upcurrent (Ambient)											Downcurrent												
Distance to Source		Approx. 500 - 1000 ft ¹											500 ft ²												
Sample ID		091317-SIDI-E-U											091317-SIDI-E-D												
Sample Time		10:27											10:04												
Parameter		Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene
								Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260		
Unit		(ppm)	(ppb)											(ppm)	(ppb)										
Detection Limit ³		Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1
Water Quality Standard ³		*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006
Analytical Result ⁴	S	32	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	25.3	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
	M	NS											NS												
	B	20.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	33.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	

Notes: ¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected at the edge of the 500 ft mixing zone

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/13/2017																								
Survey Type		V - Vessel Based																								
Construction Activity		TIDO - Timber Dolphin Removal				Comments																				
Tide		Ebb																								
Source Location		Area 1B																								
Sample Location	Upcurrent (Ambient)												Downcurrent													
Distance to Source	Approx. 500 - 1000 ft ¹												150 ft ²													
Sample ID	091317-TIDO-E-U												091317-TIDO-E-D													
Sample Time	11:14												11:03													
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene		
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260				
Unit	(ppm)	(ppb)												(ppm)	(ppb)											
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	-	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	-	0.1		
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	-	-	-	-	16	0.0006	*	0.0007	8.2	5.6	8.0	66	-	-	-	-	16	0.0006		
Analytical Result ⁴	S	NS												NS												
	M	17.6	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	26.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND			
	B	NS												NS												

Notes: ¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected as close to turbidity curtain as practicable

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/14/2017																								
Survey Type		V - Vessel Based																								
Construction Activity		SIDI - Silt Displacement				Comments																				
Tide		Ebb																								
Source Location		Bent 182																								
Sample Location		Upcurrent (Ambient)												Downcurrent												
Distance to Source		Approx. 500 - 1000 ft ¹												500 ft ²												
Sample ID		091417-SIDI-E-U												091417-SIDI-E-D												
Sample Time		09:40												09:22												
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene		
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260				
Unit	(ppm)	(ppb)												(ppm)	(ppb)											
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1		
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006		
Analytical Result ⁴	S	17.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	20.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		
	M	NS												NS												
	B	17.3	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	29.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		

Notes: ¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected at the edge of the 500ft mixing zone

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/15/2017																							
Survey Type		V - Vessel Based																							
Construction Activity		SIDI - Silt Displacement				Comments																			
Tide		Ebb																							
Source Location		B180																							
Sample Location		Upcurrent (Ambient)												Downcurrent											
Distance to Source		Approx. 500 - 1000 ft ¹												500 ft ²											
Sample ID		091517-SIDI-E-U												091517-SIDI-E-D											
Sample Time		09:39												09:21											
Parameter		Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene
								Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260		
Unit		(ppm)	(ppb)											(ppm)	(ppb)										
Detection Limit ³		Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1
Water Quality Standard ³		*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006
Analytical Result ⁴	S	10.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	10.3	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
	M	NS												NS											
	B	11	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	22	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND

Notes: ¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected at the edge of the 500 ft mixing zone

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/15/2017																						
Survey Type		V - Vessel Based																						
Construction Activity		TIDO - Timber Dolphin Removal				Comments																		
Tide		Ebb																						
Source LocationA		Approximately B20																						
Sample Location		Upcurrent (Ambient)											Downcurrent											
Distance to Source		Approx. 500 - 1000 ft ¹											150 ft ²											
Sample ID		091517-TIDO-E-U											091517-TIDO-E-D											
Sample Time		10:34											10:17											
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260		
Unit	(ppm)	(ppb)											(ppm)	(ppb)										
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006
Analytical Result ⁴	S	NS											NS											
	M	16.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	13.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
	B	NS											NS											

Notes: ¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected as close to the turbidity curtain as practicable

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/18/2017																							
Survey Type		V - Vessel Based																							
Construction Activity		SIDI - Silt Displacement				Comments																			
Tide		Flood																							
Source Location		B172																							
Location		Upcurrent (Ambient)												Downcurrent											
Distance to Source		Approx. 500 - 1000 ft ¹												500 ft ²											
Sample ID		091817-SIDI-F-U												091817-SIDI-F-D											
Sample Time		10:59												10:20											
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260			
Unit		(ppm)	(ppb)											(ppm)	(ppb)										
Detection Limit ³		Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1
Water Quality Standard ³		*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006
Analytical Result ⁴	S	20	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	29.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
	M	29.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	20.2	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
	B	44.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	20.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected at the edge of the 500 ft mixing zone

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/20/2017																								
Survey Type		B - Barge Based																								
Construction Activity		SIDI - Silt Displacement				Comments		Collected from barge because of rough river conditions																		
Tide		Flood																								
Source Location		B173																								
Sample Location		Upcurrent (Ambient)												Downcurrent												
Distance to Source		Approx. 500 - 1000 ft ¹												400 ft ²												
Sample ID		092017-SIDI-F-U												092017-SIDI-F-D												
Sample Time		11:02												10:51												
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene		
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260				
Unit	(ppm)	(ppb)												(ppm)	(ppb)											
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	-	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	-	0.1		
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	-	-	-	-	16	0.0006	*	0.0007	8.2	5.6	8.0	66	-	-	-	-	16	0.0006		
Analytical Result ⁴	S	20	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	53	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		
	M	NS												NS												
	B	18.3	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	37	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		

Notes:

¹ Samples collected up current of the source

² Samples collected from the silt displacement barge because of high winds and rough river conditions

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/20/2017																							
Survey Type		B - Barge Based																							
Construction Activity		TIDO - Timber Dolphin Removal			Comments			Collected from barge because of rough river conditions																	
Tide		Flood																							
Source Location		B9																							
Sample Location		Upcurrent (Ambient)												Downcurrent											
Distance to Source		Approx. 200 ft ¹												100 ft ²											
Sample ID		092017-TIDO-F-U												092017-TIDO-F-D											
Sample Time		09:50												09:43											
Parameter		Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene
								Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260		
Unit		(ppm)	(ppb)											(ppm)	(ppb)										
Detection Limit ³		Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1
Water Quality Standard ³		*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006
Analytical Result ⁴	S	NS												NS											
	M	66	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	65	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
	B	NS												NS											

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected as close to the turbidity curtain as practicable

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/21/2017																							
Survey Type		V - Vessel Based																							
Construction Activity		SIDI - Silt Displacement				Comments																			
Tide		Flood																							
Source Location		B175																							
Sample Location		Upcurrent (Ambient)												Downcurrent											
Distance to Source		Approx. 500 - 1000 ft ¹												500 ft ²											
Sample ID		092117-SIDI-F-U												092117-SIDI-F-D											
Sample Time		09:51												09:23											
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260			
Unit		(ppm)	(ppb)											(ppm)	(ppb)										
Detection Limit ³		Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1
Water Quality Standard ³		*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006
Analytical Result ⁴	S	14.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	18	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
	M	41	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	24	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
	B	49.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	37.3	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected at the edge of the 500 ft mixing zone

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/21/2017																								
Survey Type		V - Vessel Based																								
Construction Activity		TIDO - Timber Dolphin Removal				Comments																				
Tide		Flood																								
Source Location		B10																								
Sample Location		Upcurrent (Ambient)												Downcurrent												
Distance to Source		Approx. 500 - 1000 ft ¹												75 ft ²												
Sample ID		092117-TIDO-F-U												092117-TIDO-F-D												
Sample Time		10:26												10:20												
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene		
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260				
Unit	(ppm)	(ppb)												(ppm)	(ppb)											
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1		
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006		
Analytical Result ⁴	S	NS												NS												
	M	58.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	54	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		
	B	NS												NS												

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected as close to the turbidity curtain as practicable

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/22/2017																							
Survey Type		V - Vessel Based																							
Construction Activity		SIDI - Silt Displacement				Comments																			
Tide		Flood																							
Source Location		B178																							
Sample Location		Upcurrent (Ambient)												Downcurrent											
Distance to Source		Approx. 500 - 1000 ft ¹												500 ft ²											
Sample ID		092217-SIDI-F-U												092217-SIDI-F-D											
Sample Time		09:46												09:14											
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260			
Unit		(ppm)	(ppb)											(ppm)	(ppb)										
Detection Limit ³		Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1
Water Quality Standard ³		*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006
Analytical Result ⁴	S	17.6	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	17.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
	M	25.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	20	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
	B	21.2	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	93	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected at the edge of the 500 ft mixing zone

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/25/2017																								
Survey Type		V - Vessel Based																								
Construction Activity		TIDO - Timber Dolphin Removal				Comments																				
Tide		Flood																								
Source Location		B9																								
Sample Location		Upcurrent (Ambient)												Downcurrent												
Distance to Source		Approx. 500 - 1000 ft ¹												300 ft ²												
Sample ID		092517-TIDO-F-U												092517-TIDO-F-D												
Sample Time		13:29												13:15												
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene		
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260				
Unit	(ppm)	(ppb)												(ppm)	(ppb)											
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1		
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006		
Analytical Result ⁴	S	NS												NS												
	M	23.3	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	65	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		
	B	NS												NS												

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected as close to the turbidity curtain as practicable

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/26/2017																								
Survey Type		V - Vessel Based																								
Construction Activity		TIDO - Timber Dolphin Removal				Comments																				
Tide		Ebb																								
Source Location		B32																								
Sample Location	Upcurrent (Ambient)												Downcurrent													
Distance to Source	Approx. 500 - 1000 ft ¹												180 ft ²													
Sample ID	092617-TIDO-E-U												092617-TIDO-E-D													
Sample Time	09:29												09:15													
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene		
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260				
Unit	(ppm)	(ppb)												(ppm)	(ppb)											
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	-	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1		
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	-	-	-	-	16	0.0006	*	0.0007	8.2	5.6	8.0	66	-	-	-	-	16	0.0006		
Analytical Result ⁴	S	NS												NS												
	M	11.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	13.7	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND			
	B	NS												NS												

Notes: ¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected as close to the turbidity curtain as practicable

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/27/2017																							
Survey Type		V - Vessel Based																							
Construction Activity		TIDO - Timber Dolphin Removal				Comments																			
Tide		Ebb																							
Source Location		B33																							
Sample Location		Upcurrent (Ambient)											Downcurrent												
Distance to Source		Approx. 500 - 1000 ft ¹											90 ft ²												
Sample ID		092717-TIDO-E-U											092717-TIDO-E-D												
Sample Time		09:07											08:56												
Parameter		Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene
								Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260		
Unit		(ppm)	(ppb)											(ppm)	(ppb)										
Detection Limit ³		Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1
Water Quality Standard ³		*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006
Analytical Result ⁴	S	NS											NS												
	M	12	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	18.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	
	B	NS											NS												

Notes: ¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected as close to the turbidity curtain as practicable

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/11/2017																								
Survey Type		V - Vessel Based																								
Construction Activity		SIDI - Silt Displacement			Comments																					
Tide		Ebb																								
Source Location		Bent 170																								
Sample Location		Upcurrent (Ambient)												Downcurrent												
Distance to Source		Approx. 500 - 1000 ft ¹												500 ft ²												
Sample ID		091117-SIDI-E-U												091117-SIDI-E-D												
Sample Time		10:33												09:58												
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene		
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260				
Unit	(ppm)	(ppb)												(ppm)	(ppb)											
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1		
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	--	--	-	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006		
Analytical Result ⁴	S	19.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	22	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		
	M	27	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	40.7	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		
	B	35.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	53.3	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND		

Notes: ¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible

² Samples collected at the edge of the 500 ft mixing zone

³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14

⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/13/2017																						
Survey Type		V - Vessel Based																						
Construction Activity		SIDI - Silt Displacement			Comments																			
Tide		Ebb																						
Source Location		Bent 182																						
Sample Location		Upcurrent (Ambient)											Downcurrent											
Distance to Source		Approx. 500 - 1000 ft ¹											500 ft ²											
Sample ID		091317-SIDI-E-U											091317-SIDI-E-D											
Sample Time		10:27											10:04											
Parameter	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene
							Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260		
Unit	(ppm)	(ppb)											(ppm)	(ppb)										
Detection Limit ³	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1
Water Quality Standard ³	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006
Analytical Result ⁴	S	32	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	25.3	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
	M	NS											NS											
	B	20.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	33.5	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible² Samples collected at the edge of the 500 ft mixing zone³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.

Survey Date		09/14/2017																							
Survey Type		V - Vessel Based																							
Construction Activity		SIDI - Silt Displacement				Comments																			
Tide		Ebb																							
Source Location		Bent 181																							
Sample Location		Upcurrent (Ambient)												Downcurrent											
Distance to Source		Approx. 500 - 1000 ft ¹												500 ft ²											
Sample ID		091417-SIDI-E-U												091417-SIDI-E-D											
Sample Time		09:40												09:22											
Parameter		Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene	Total Suspended Solids	Mercury	Nickel	Copper	Lead	Zinc	PCB				Naphthalene	Benzo(a)pyrene
								Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260									Aroclor 1242	Aroclor 1248	Aroclor 1254	Aroclor 1260		
Unit		(ppm)	(ppb)											(ppm)	(ppb)										
Detection Limit ³		Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1	Ambient + 100	0.07	3.7	2.6	1.8	5.6	0.2	0.2	0.2	0.2	--	0.1
Water Quality Standard ³		*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006	*	0.0007	8.2	5.6	8.0	66	--	--	--	--	16	0.0006
Analytical Result ⁴	S	17.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	20.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND
	M	NS												NS											
	B	17.3	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	29.8	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND	ND

Notes:

¹ Samples collected at a location up current of the source where the water quality effects of the project are no longer discernible² Samples collected at the edge of the 500ft mixing zone³ Based on New York State Department of Environmental Conservation (NYSDEC) Permit Facility ID 3-9903-00043/00012-14⁴ S = Near Surface, M = Mid-Depth, B = Near Bottom

-- No detection limit or water quality standard

* None from sewage, industrial waste or other wastes that will cause deposition or impair the waters for their best usages

ND = Not Detected

NS = Not Sampled due to water depth, pursuant to 8/6/13 modification to Condition 60 of NYSDEC Permit Facility ID 3-9903-00043/00012-14.